
## POTEAU D'INCENDIE



## Inspection and Testing Report

Contract No: NIE6226/09

Description: LANDING FIRE HYDRANT SS100/65-1.6

No.	Item	Inspection content	Result	Date	Inspector	Remark
	Performance Test	No visible leakage or structural damage	ок	X.	10	
	Shell Test					
	Medium	Water	OK			
	Test pressure (MPa)	1. 6				
	Duration	180s	ок			
	Seal Test	21				
	Medium	Water	ок			
	Test pressure(MPa)	2. 4	ок			
	Duration	60s	ок			
	Leakage	0 -	ок			
	Operation Test	No block from fully open to close 3 times	ок			
	Packing	Each piece into one polybag, then put in one nylon bag, and after put in one cotton bag.	ок			
						9.80
	2					